



*All Pictures shown are for illustration purpose only. Actual product may vary.

Features

- 100% OE Quality
- Strict product inspection by OE criteria
- High reliability by years of experience as a Driveshaft manufacturer

Parts/Vehicle Information

Genuine Part No.	JTEKT Part No.	Part	Vehicle Model	Vehicle Model code
42330-22091	JC030-000230	SHAFT ASSY, RR DRIVE	IS, MARK X	GSE20, GRX120
42340-22181	JC040-000090	SHAFT ASSY, RR DRIVE	IS, MARK X	GSE20, GRX120
43430-60040	43430-60040	SHAFT ASSY, FR DRIVE	LAND CRUISER80/100(1998-2007), LX470	UZJ100W, HDJ100W
43430-60082	JC010-000292	SHAFT ASSY, FR DRIVE	HILUX, PRADO(2009-), FJ CRUISER, GX	GRJ150W, GDJ150W, TJD150W, GSJ15W, UZJ120
04427-52A22	JC091-002582	BOOT KIT, FR DRIVE	VITZ/YARIS (2010-)	KSP130, NCP131, NHP130, NSP13#
04427-60141	JC091-001931	BOOT KIT, FR DRIVE	HILUX, PRADO(2002-2009), FJ CRUISER, GX	GRJ120, KDJ120, RZJ120, TRJ120, VZJ120, GSJ15W, UZJ120
04437-60042	JC091-001941	BOOT KIT, FR DRIVE	HILUX SURF (2002-2009)	GRN215, KDN215, RZN215, TRN215, VZN215
04427-60120	JC091-000590	BOOT KIT, FR DRIVE	LAND CRUISER80/100(1998-2007) LX470	GH-UZJ, HDJ100W
04437-60090	JC091-001740	BOOT KIT, FR DRIVE	HILUX, PRADO(2009-), FJ CRUISER, GX	GRJ120, KDJ120, RZJ120, TRJ120, VZJ120, GSJ15W, UZJ120
04439-12014	JC091-000053	BOOT KIT, RR DRIVE	ALPHARD (2008-2015)	ANH25W, ATH20, GGH20

Continued overleaf ▼

Genuine Part No.	JTEKT Part No.	Part	Vehicle Model	Vehicle Model code
43420-0D560	JC020-001390-A	SHAFT ASSY, FR DRIVE, LH	YARIS/VIOS (2013-) 1.5L CVT	NSP150
43420-0D280	JC020-001400-A	SHAFT ASSY, FR DRIVE, LH	YARIS/VIOS (2013-) 1.3L CVT/MT, 1.5L MT	NSP150
43410-0D700	JC010-001970-A	SHAFT ASSY, FR DRIVE, RH	YARIS/VIOS (2017-)	NSP151
43410-0D260	JC010-001980-A	SHAFT ASSY, FR DRIVE, RH	YARIS/VIOS (2013-2017) 1.3L MT, 1.5L CVT/MT	NSP150
43410-0D570	JC010-001990-A	SHAFT ASSY, FR DRIVE, RH	YARIS/VIOS (2013-2017) 1.3L CVT	NSP150
-	JC091-006040-A	BOOT KIT, CV JOINT IN	YARIS/VIOS (2013-)	NSP150, NSP151
-	JC091-006050-A	BOOT KIT, CV JOINT OUT	YARIS/VIOS (2013-)	NSP150, NSP151
43405-0D310	JC003-003000-A	JOINT SUB-ASSY, CV JOINT	YARIS/VIOS (2013-)	NSP150, NSP151
43410-02C60	JC010-001510-A	SHAFT ASSY, FR DRIVE, RH	COROLLA ALTIS	E210
43410-02C71	JC010-001521-A	SHAFT ASSY, FR DRIVE, RH	COROLLA ALTIS	E210
43420-02F60	JC020-001070-A	SHAFT ASSY, FR DRIVE, LH	COROLLA ALTIS	E210
43420-02F70	JC020-001080-A	SHAFT ASSY, FR DRIVE, LH	COROLLA ALTIS	E210
43410-0A070	JC010-001580	SHAFT ASSY, FR DRIVE, RH	COROLLA CROSS	ZVG10
43410-0A080	JC010-001590	SHAFT ASSY, FR DRIVE, RH	COROLLA CROSS	ZVG10
43420-0A070	JC020-001120	SHAFT ASSY, FR DRIVE, LH	COROLLA CROSS	ZVG10
43420-0A080	JC020-001130	SHAFT ASSY, FR DRIVE, LH	COROLLA CROSS	ZVG10
04437-0D390	JC091-005690-A	BOOT KIT, FR DRIVE SHAFT IN, JT, RH	COROLLA ALTIS, COROLLA CROSS	E210, ZVG10
04428-0D541	JC091-005680-A	BOOT KIT, FR DRIVE SHAFT IN & OUT JT, LH	COROLLA ALTIS, COROLLA CROSS	E210, ZVG10
04428-0D540/542	JC091-005681	BOOT KIT, FR DRIVE SHAFT IN & OUT JT, LH	COROLLA ALTIS, COROLLA CROSS	E210, ZVG10
04428-0D402	JC091-004671	BOOT KIT, FR DRIVE SHAFT IN & OUT JT, LH	COROLLA ALTIS, COROLLA CROSS	E210, ZVG10
04428-0D392	JC091-004651	BOOT KIT, FR DRIVE SHAFT IN & OUT JT, LH	COROLLA ALTIS, COROLLA CROSS	E210, ZVG10
04427-0D422	JC091-004661	BOOT KIT, FR DRIVE SHAFT IN & OUT JT, RH	COROLLA ALTIS, COROLLA CROSS	E210, ZVG10
04427-0D560/562	JC091-005671	BOOT KIT, FR DRIVE SHAFT IN & OUT JT, RH	COROLLA ALTIS, COROLLA CROSS	E210, ZVG10
04427-0D561	JC091-005670-A	BOOT KIT, FR DRIVE SHAFT IN & OUT JT, RH	COROLLA ALTIS, COROLLA CROSS	E210, ZVG10
04427-0D412	JC091-004641	BOOT KIT, FR DRIVE SHAFT IN & OUT JT, RH	COROLLA ALTIS, COROLLA CROSS	E210, ZVG10



Website

CAT.NO.AM0003-0

Although care has been taken to ensure correctness of the information contained in this sheet, JTEKT share in no event accepts liability for any damage or losses suffered due to any errors and/or omissions.

STOP Driveshaft Imitations!!

JTEKT

Product structure comparison

JTEKT



Coating
Resin boots
2 dampers
7,100g


Imitation



No coating
Rubber boots
1 damper
6,155g


May cause...
Rust Break

Strength Test



10.4% Lower Strength than JTEKT

Durability Test



48% Lower Durability than JTEKT



Choose JTEKT Driveshaft for safe driving.

CAT.NO.AM0003-0



*All Pictures shown are for illustration purpose only. Actual product may vary.

Features

- 100% OE Quality
- Strict product inspection by OE criteria
- High reliability by years of experience as a Driveshaft manufacturer

Parts/Vehicle Information

Genuine Part No.	JTEKT Part No.	Vehicle Model	Vehicle Model code
44310-60520	0-P1310-60090	LAND CRUISER(2007-)	GRJ200, URJ20#, UZJ200, VDJ200
44310-60510	0-P1310-60060	LAND CRUISER(2007-2017)	GRJ200, URJ20#, UZJ200, VDJ200
44310-26371	JF001-000830	HIACE(2005-)	KDH2, TRH2, LH2
44310-35660	44310-35660	HILUX SURF(2002-2010), FJ CRUISER LAND CRUISER PRADO, 4RUNNER	GRN215, KDN215, RZN21#, TRN21#, VZN21#, GRJ12#, KDJ12#, RZJ12#, TRJ12#, VZJ12#, GSJ1#, LJ12#, RZJ12#, TRJ12#, GRN21#, UZN21#
44310-33170	0-P1310-33010	LEXUS ES240/350, CAMRY(2006-)	ACV40, GSV40
44310-60500	0-P1310-60100	LAND CRUISER(2007-)	URJ202, UZJ200, VDJ200
44320-48040	44320-48040	HIGHLANDER, LEXUSRX300/330/350 KLUGER(2003-2007), HURRIER	ACU2, MCU2, MCU3, GSU3, MCU28, ACU3, GSU3, MCU3
44310-60460	0-P1310-60040	LAND CRUISER(2007-)	FJZ7, GRJ7, HZJ7, VDJ7
44310-60590	JF001-000420	LAND CRUISER200(2007-2012) LEXUS LX	URJ202, UZJ200, VDJ200, GRJ200, URJ20#, UZJ200, VDJ200
44310-60580	JF001-000310	LAND CRUISER(2007-)	FZJ7#, GRJ7#, HZJ7#, VDJ7#

Continued overleaf ▼

Genuine Part No.	JTEKT Part No.	Vehicle Model	Vehicle Model code
44310-60530	0-P1310-60110	LAND CRUISER(2007-)	GRJ200, URJ20#, UZJ200, VDJ200
44310-60400	44310-60400	LAND CRUISER100(1998-2007)	FZJ10, HDJ100, UZJ100, UZJ100
44310-60480	0-P1310-60070	LAND CRUISER200(2007-2012) LEXUS LX	URJ200, UZJ200, VZJ200, GRJ200, VDZ200
44320-36240	44320-36240	COASTER(1993-)	BB4#/5#, BZB40/50, HZB50, RZB40/50, TRB40/50, XZB4#/5#
44310-60542	JF001-000242	PRADO/4RUNNER(2009-)	GRJ150, KDJ150, LJ150, TRJ15#, GRN28
44310-60552	JF001-000252	PRADO(2009-)	GRJ150, KDJ150, LJ150, TRJ15#
44310-60563	JF001-000263	PRADO(2009-)	GRJ150L, GKA*KC, TRJ150L, GK*EKC GRJ150, KDJ150, LJ150, TRJ15#
44310-35690	44310-35690	HILUX SURF(2002-2009) LAND CRUISER, PRADO	GRN215, KDN215, RZN21#, TRN21#, VZN21# GRJ12#, KDJ12#, RZJ12#, TRJ12#, VZJ12#
44310-60320	44310-60320	LAND CRUISER100(1998-2007)	FZJ10#, HDJ100, HZJ105, UZJ100
44320-33140	44320-33140	WINDOM, CAMRY, LEXUS ES300(2001-2006)	MCV30, ACV30, MCV3#, MCV3#
44310-35710	44310-35710	HILUX SURF, LAND CRUISER, PRADO(2002-2010)	GRJ12#, KDJ120, KZJ120, LJ12#, RZJ12#, TRJ12#, GRJ150, KDJ150, LJ150, TRJ15# GRN215, KDN215, RZN21#, TRN21#, VZN21#, GRJ12#, KDJ12#, RZJ12#, TRJ12#, VZJ12#
44310-28270	0-P1310-28020	IPSUM, NOAH, VOXY, PICNIC, AVENSIS, VERCO(2001-2009)	ACM2, AXR6
44310-60410	44310-60410	LAND CRUISER100(1998-2007)	FZJ10, HDJ100, HZJ105, UZJ100
44320-60310	44320-60310	LAND CRUISER100 LEXUS LX470(1998-2007)	UZJ100, HDJ100
44310-60390	44310-60390	LAND CRUISER100 LEXUS LX470(1998-2007)	UZJ100, HDJ100
44310-48070	0-P1310-48010	LEXUS RX330/350 HARRIER(2003-2008)	MCU3/GSU3 ACU3, GSU3, MCU3
44310-50070	44310-50070	CELSIOR/LEXUS LS430(2000-2006)	UCF3
44320-35490	44320-35490	HILUX 4RUNNER(1995-2002)	KDN185, KZN185, RZN18#, VZN18#
44320-60380	0-P1320-60010	LAND CRUISER70(2007-)	FZJ7#, GRJ7#, HZJ7#, VDJ7#
44310-33180	0-P1310-33020	CAMRY(2006-2011)	ACV40, GSV40
44320-36250	44320-36250	COASTER(1993-)	BB4#/5#, BZB40/50, HZB50, RZB40/50, TRB40/50, XZB4#/5#, BB5, RZB5, TRB53, XZB53



Website

CAT.NO.AM0004-0

Although care has been taken to ensure correctness of the information contained in this sheet, JTEKT share in no event accepts liability for any damage or losses suffered due to any errors and/or omissions.